


Failed attempt using curtainwall system tool by face in doing UNITIZED PANEL



see fig 2 the blow-up clouded area view from inside of curtainwall




fig 2

Using curtain wall system tool by face, when i make the unitized panel the connection between mullion and transom are not good as it should be.

mullion and transom bad connection




fig 3




fig 4

