

failed attempt using adaptive panel, please take note that i used one profile only around the panel.





fig 1

see blow-up in fig 2



the mullion of two adjacent panel should be parallel but as the angle between panels are inward the back of mullions are separating from each other




fig 3

the mullion of two adjacent panel should be parallel but as the angle between panels are outward the back of mullions are overlapping from each other




fig 4