This window does not flip when I use the window flip control,
as in the corner that is cut off at the bottom will not flip to
suit the other side of this dormer!!

PROPOSED DORMER WINDOW
ROOF

DOOR, WINDOW
& BALCONY

SETBACK FROM
REAR BOUNDARY

1000

EXISTING 2 STOREY BUILING AT
LOT 268 HALTER LANE

PROPOSED NEW ATTACHED
GARAGE

WINDOWS AT EXISTING
BUILDING

EXISTING "LILLAHEM" BUILDING

Loft
▼

5020

1st Floor
▼

2520

4287

3200

2837

Ground Floor
▼

0

Site Level
▼

-900

EXISTING TREES TO REMAIN

PROPOSED NEW STONEWORK
TO ENTRY & GARAGE FACADE
TO BE LOCAL STONE OR
GLENROWAN GRANITE

EXISTING TREE TO REMAIN