BEAM DISPLAYED CORRECTLY

BEAM DISPLAYING IN ELEVATION
VIEW EVEN THOUGH THE
SECTION LINE CUTS THROUGH IT