

Lost in effing Revit (pardon my french)

Its gone. Here are 17 places to look.

Basics

1. **Visibility graphics** – Is the category on (V V)
2. Are you zoomed in or out too far? **Zoom all** – (ZE or ZF)
3. Is it **hidden in the view** – Use the lightbulb on the bottom toolbar
4. Is it **temporarily hidden** – Look for cyan border on screen. Use glasses on bottom toolbar
5. Is the **workset** on?
6. Is it in the right **workset** – Note copying an item will put it in the current workset not the same workset as the original.
7. Is the **workset** turned off in the **view** (V V)
8. Is it outside the **crop region** – show crop region to check – blue icon on bottom toolbar
9. Is the **view depth** setting set up to show it. (VP)
10. Was it inserted on a **level** different from what you expected
11. Is the **detail level** setting ok – Square icon on bottom toolbar
12. Is the **phase** set correctly? May be in a different phase – Existing demo or new construction (VP)
13. Are the **phase filters** set up correctly (VP)
14. Were **invisible lines** used eg in a filled region
15. Is it a mass with the **mass category turned off** – Icon on top toolbar beside 3D house icon
16. If a pasted **detail object is mostly outside the view crop region** it will not be visible. Turn off crop.
17. It might be excluded from a group instance (will show up when you hover over the group) Select the group and right click to restore all excluded

Some things to try

Create a new 3D view so there are no visibility setting adjusted – Temporarily turn off items or categories to see if its hidden or use a section box

Use wireframe setting on bottom toolbar

Temporarily turn off items or categories to see if its hidden

Turn on all worksets

Happy searching. Matt Cantwell